

PROJECT: SRMS

ASS'Y NOMENCLATURE: BACK-UP

SHEET: 1

REF. REV.	NAME, GTY, & DRAWING REF. DESIGNATION	FATEURE WODE AND CAUSE	FATLURE EFFECT ON END ITEM	NOWR / FUNC.  1/1 RATIONALE FOR ACCEPTANCE  CRITICALITY
4450 0	BACKUP DRIVE SWITCH QTY-1 P/N NE625-0102- 7405	HODE: LOSS OF BACKUP DRIVE.  CAUSE(S): (1) SWITCH FAILS IN OFF POSITION. (2) SWITCH FAILS IN + OR - DIRECTIONS.	CAUSE (2) WHEN BACKUP SELECTED. SELECTED JOINT WILL DRIVE.  WORST CASE UMEMPECTED MOTION. JOINT RUMANAY. UMAMMUNCIATED. CREW ACTION REQUIRED. REDUNDANT PATHS REMAINING N/A	TOGGLE SMITCHES USED ON THE DEC PAMEL ARE MERMETICALLY SEALED, AND OF A MATURE AND PROVEN DESIGN. THESE SMITCHES ARE IN COMMON USE ON THE ORBITER VEHICLE.  THE SMITCHES ARE CONTROLLED BY ROCKWELL INTERNATIONAL SPECIFICATION MC 652-0102 AND HAVE BEEN QUALIFIED TO THE REQUIREMENTS OF THIS SPECIFICATION.  ELECTRICAL CONNECTIONS TO THE SMITCH ARE ACHIEVED BY MEANS OF SOLDERABLE TERNIMALS.  MIRING TO SMITCH TERMINALS UTBLIZES HICKEL PLATED CONDUCTORS WITH A POLYAMID INSULATION. SOLDERING OF THE NICKEL PLATED WIRE TO THE SMITCH TERNIMALS IS CONTROLLED BY CAE PROCESS SPECIFICATION PD 91059.  THE MIRING HARNESS IS DESIGNED TO BE CAPABLE OF SEPARATE TESTING (FOR INSULATION RESISTANCE, DIELECTRIC STRENGTH, AND CONTINUITY).  MOUNTING OF THE SMITCH TO THE DEC PAMEL IS BY MEANS OF A 15/32 MIT WHICH ENGAGES A THREADED BUSHING ON THE SWITCH. A KEYED WASHER PROVIDES BOTATION RESTRAINT, AFTER INSTALLATION AND TORQUING, THE MULT STAKED TO THE PAMEL BY A BLOOD OF POWY ADHESIVE, A STAILLESS STEEL GUARD PROTECTS THE SMITCH LEVER AGAINST DANAGE OR INAUVERTENT OPERATION.  ANALYSIS OF THE BASIC PAMEL STRUCTURE MAS DEMONSTRATED THAT THERE ARE NO RESONANCES IN THE RELEVANT VIBRATION FREQUENCY SPECTRUM. THIS ANALYSIS HAS BEEN VERIFIED BY VIBRATION TESTING OF THE DAC PAMEL ASSEMBLY.  APPLICATION ANALYSIS HAS CONFIRMED THAT ADEQUATE ELECTRICAL STRESS MARGINS ARE ACHIEVED.  AT THE PART LEVEL, QUALIFICATION/CERTIFICATION MC452-0102. THIS TEST REQUIREMENT INCLUDES: INSULATION MESISTANCE, DIELECTRIC STRENGTH, FOR SMITCH OPERATIONAL CYCLES REFER TO TABLE 13.  ALL UNITS ARE SUBJECTED TO ACCEPTANCE TESTS MICH INCLUDE PREFACCEPTANCE RING THE JUSTICAL THAN THE DESIGN ARE SUBJECTED TO ACCEPTANCE VERSATION, SEAL TEST, VISUAL EXAMINATION, AND RADIOGRAPHIC INSPECTION.  ALL BESISTORS AND CAPACITORS USED IN THE DESIGN ARE SELECTED FROM ESTABLISHED RELIABILITY (ER) TYPES. LIFE EXPECTANCY IS INCREASED BY ENSURING THAN THAN THAN THAN THAN THAN THAN THAN

REPARED BY: MFWG	SUPERCEDING DATE: 11 SEP 86	APPROVED BY:	DATE:
------------------	-----------------------------	--------------	-------

## CRITICAL ITEMS LIST

PROJECT: SRMS

ASS'Y NOMENCLATURE: BACK-UP

SYSTEM: BACK-UP

ASS'Y P/N:

S


FMEA REF.	REV.	NAME UTY E DRAWING RÉF. DESIGNATION	FAYLURE HODE AND CAUSE	FAILURE EFFECT ON END ITEN	HOUR / FUNC. 1/1 RATIONALE FOR ACCEPTANCE CRITICALITY
4450	0	BACKUP DRIVE SWITCH GTY-1 P/N ME425-0102- 7405	MODE: LOSS OF BACKUP ORIVE.  CAUSE(S): (1) SMITCH FAZLS IN OFF POSITION.  (2) SMITCH FAILS IN + OR - DIRECTIONS.	CAUSE (1) LOSS OF BACKUP DRIVE.  CAUSE (2) WHEN BACKUP SELECTED JOINT WILL ORIVE.  WORST CASE LINEXPECTED HOTION. JOINT RUHAMAY. LUMANMUNCTATED. CREW ACTION REQUIRED.  REDUNDANT PATHS REMAINING N/A	ACCEPTANCE TESTS  THE HARDWARE ITEM IS SUBJECTED TO THE FOLLOWING ACCEPTANCE ENVIRONMENTAL TESTS AS PART OF THE DAC PANEL ASSEMBLY.  O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 1  O THERMAL: +110 DEGREES F TO PLUS 10 DEGREES F (2 CYCLES - 9.5 NRS/CYCLE.)  THE DAC PANEL ASSEMBLY IS FURTHER TESTED AS PART OF THE RNS SYSTEM TESTS (TIPSTE RNS SYSTEM TESTS (TIPSTE RNS SYSTEM) THE SYSTEM TESTS (TIPSTE RNS SYSTEM) THE FAILURE MODE.  QUALIFICATION TESTS  THE SMITCH ITEM MAS BEEN GUALIFIED FOR ORBITER USE. THE DAC PANEL ASSEMBLY HAS BEEN SUBJECTED TO THE FOLLOWING QUALIFICATION TEST ENVIRONMENTS.  O VIBRATION: LEVEL AND DURATION - REFERENCE TABLE 1  O SHOCK: 20G/11 MS - 3 AXES (6 DIRECTIONS)  O THERMAL: 130 DEGREES F TO -23 DEGREES F (12 HRS PER CYCLE) (6 CYCLES)  O HUMIDITY: 95% (120 DEGREES F TO B2 DEGREES F CYCLE IN 16 HRS) 10 CYCLES TOTAL.  O ENC: MIL-STD-461 AS MODIFIED BY SL-E-0002 (TEST CEOT, CEO2, CEO3, CSO1 (DC/AC), CSO2, CSO6, REO2 (B/M), RSO2, RSO3, FLIGHT CHECKOUT  PDRS OPS CHECKLEST (ALL VEHICLES) JSC 16987
			l	1	PMS/RACK-IIP 22

PREPARED BY: MFMG

SUPERCEDING DATE: 11 SEP 86

APPROVED BY:

RMS/BACK-UP 22



PROJECT: SRMS ASS'Y NOMENCLATURE: BACK-UP SYSTEM: BACK-UP ASS'Y P/N:

REF. REV.	DRAWING REF. DESIGNATION	FATLURE MODE AND CAUSE	FAILURE EFFECT ON END ITEM	HOUR / FUNC.  1/1 RATIONALE FOR ACCEPTANCE  CRITICALITY
4450 0	BACKUP DRIVE SMITCH GTY-1 P/N ME425-0102- 7405	MODE: LOSS OF BACKUP DRIVE.  CAUSE(S): (1) SWITCH FAILS IN OFF POSITION.  (2) SWITCH FAILS IN + OR - DIRECTIONS.	CAUSE (1) LOSS OF BACKUP DRIVE.  CAUSE (2) WHEN BACKUP SELECTED JOINT WILL DRIVE.  MORST CASE UNEXPECTED MOTION. JOINT RUMANAY. UNANNUNCIATED. CREW ACTION REQUIRED. REDUNDANT PATHS REMAINING N/A	HERMETICALLY SEALED TOGGLE SUITCHES ARE PROCURED TO ROCKWELL SPECIFICATION MAD ACCEPTANCE TESTING OF SMITCHES IS PERFORMED TO R.1. SPEC. MC432-0102.  RECEIVING INSPECTION VERIFIES THAT SMITCHES RECEIVED ARE AS IDENTIFIED IN THE PROCUREMENT DOCUMENTS, THAT MO PHYSICAL DAMAGE MAS OCCURRED TO SMITCHES DURING SHIPMENT, THAT THE RECEIVING DOCUMENTS PROVIDE ADEQUATE TRACEBULITY INFORMATION AND ACCEPTANCE TEST DATA IDENTIFIES ACCEPTABLE PARTS.  PARTS ARE INSPECTED THROUGHOUT MANUFACTURE AND ASSEMBLY AS APPROPRIATE TO THE MANUFACTURING STAGE COMPLETED. THESE INSPECTIONS INCLUDE, USE TO SMITCH CONTACTS WIRE ROUTING, STRESS RELIEF OF WIRES TO SMITCH CONTACTS WIRE ROUTING, STRESS RELIEF OF WIRES TO SMITCH CONTACTS WIRE ROUTING, STRESS RELIEF OF WIRES TO SMITCH CONTACTS AND INSPECTION, AS BUILD COMFIGURATION MASA NHB \$300.4(3A) STAMBARD, AS MODIFIED BY JSCORBOODA.  PRE-TEST INSPECTION OF DRE PAMEL ASSY INCLUDES AN AUDIT OF LOWER TIER INSPECTION COMPLETION, AS BUILD COMFIGURATION VERIFICATION TO AS DESIGN ETC. (SPAR/GOVERNMENT REP. MANOATORY INSPECTION POINT)  A TEST READINESS REVIEW (TRR) WHICH INCLUDES VERIFICATION OF TEST PERSONNEL, TEST DOCUMENTS, TEST EQUIPMENT CALLBRATION/VALIDATION STATUS AND HARDMARE CONFIGURATION IS CONVENED BY QUALITY ASSURANCE IN COMMUNICTION WITH ENCINEERING CONVENED BY QUALITY ASSURANCE IN COMMUNICTION WITH ENCINEERING CONVENED BY AND ALBOHAMEN REPRESENTATIVE PRIOR TO THE START OF ANY FORMAL TESTING (ACCEPTANCE OR QUALIFICATION, UNICH INCLUDES GROUNDING CHECKS, INFER CONNECT CABLE VERIFICATION, CONNECTOR INSPECTION FOR BEN'T OR PUSHBACK CONTACTS ETC.  SUB-SYSTEM SINTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABLE CUIT FICATION, CONNECTOR INSPECTION FOR BEN'T OR PUSHBACK CONTACTS ETC.  SUB-SYSTEM SINTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABLE PURIFICATION, CONNECTOR INSPECTION FOR BEN'T OR PUSHBACK CONTACTS ETC.  SEMS SYSTEMS INTEGRATION, THE INTEGRATION OF MECHANICAL ARM SUBASSEMBLIES AND THE FLIGHT CABLE CUIT FINE CONTROL OF SE

PREPARED BY: NEUG		
HEINNED BI: MING	SUPERCEDING DATE: 11 SEP 86	APPROVED RY:

## CRITICAL ITEMS LIST

SYSTEM: BACK-UP
ASS'Y P/N: SHEET: 4 PROJECT: SRMS ASS'Y NOMENCLATURE: BACK-UP

FREA REF.	REV.	NAME GTY E DRAWING RÉF. DESIGNATION	FATLURE NODE AND CAUSE	FATLURE EFFECT ON END ITEM	HOUR / FUNC. 1/1 RATIONALE FOR ACCEPTANCE CRITICALITY	<del></del>
4450	0	BACKUP BRIVE SWITCH QTY-1 P/N ME425-0102- 7405	MODE: LOSS OF BACKUP DRIVE. CAUSE(S): (1) SWITCH FAILS IN	CAUSE (1) LOSS OF BACKUP DRIVE.  CAUSE (2) WHEN BACKUP SELECTED.	FAILURE HISTORY  NO EEE PARTS FAILURES HAVE OCCURRED SUBSEQUENT TO ASSEME PARTS.	BLY OF
:			POSITION.  (2) SWITCH FAILS IN + OR - DIRECTIONS.	SELECTED JOINT WILL DRIVE. WORST CASE UNEXPECTED NOTION. JOINT RUMANAY. UNANWANCIATED. CREW ACTION		
				REQUIRED.  REDUNDANT PATHS REMAINING		
,**						
·					RMS/BACK-UP 24	

PREPARED BY: MEMG SUPERCEDING DATE: 11 SEP 86

APPROVED BY:

## CRITICAL ITEMS LIST

PROJECT: SRMS ASS'Y NOMENCLATURE: BACK-UP

SYSTEM: BACK-UP
ASS'Y P/N: \_\_\_\_\_ SHEET: 5

A450 0 SACKUP PRIVE. SUITCE 17/1 PARCE 25-1012- TOSS OF ACKUP PORTION.  CAUSE (2): (1) SUITCH PORTION.  CAUSE (2): (2) SUITCH PORTION.  CAUSE (2): (3) SUITCH PORTION.  CAUSE (2): (4) SUITCH PORTION.  CAUSE (2): (4) SUITCH PORTION.  CAUSE (2): (5) SUITCH PORTION.  CAUSE (2): (6) SUITCH PORTION.  CAUSE (2): (1) SUITCH PORTION.  CAUSE (2): (2) SUITCH	FMEA REF.	REV.	WAHE DIY E DRAWING REF. DESIGNATION	FATEURE MODE AND CAUSE	FATEURE EFFECT ON END LIEM	HOUR / FUNC.  1/1  CRITICALITY  RATIONALE FOR ACCEPTANCE
	4450		SWITCH QTY-1 P/N ME425-0102-	LOSS OF BACKUP ORIVE.  CAUSE(S): (1) SWITCH FAILS IN OFF POSITION. (2) SWITCH FAILS IN + OR DIRECTIONS.	CAUSE (2) WHEN BACKUP SELECTED. SELECTED JOINT WILL DRIVE. WORST CASE UMEXPECTED MOTION. JOINT RUMANAY. UMANHUNCIATED. CREW ACTION REQUIRED. REPLIMOANT PATHS REMAINING	OPERATIONAL EFFECTS  JOINT DRIVES WITHOUT A COMMAND.  CREW ACTION  POWER SW TO OFF.  CREW SHOULD BE TRAINED TO ALWAYS OBSERVE WHETHER THE ARM IS RESPONDING PROPERLY TO COMMANDS. IF JT ISN'T, THEN THE RMS  POWER SMITCH SHOULD BE TURNED OFF.  MISSION CONSTRAINT  THE OPERATOR MUST BE ABLE TO DETECT THAT THE ARM IS RESPONDING PROPERLY TO COMMANDS VIA WINDOW AND/OR CCTV VIEWS DURING ALL  SCREEN FAILURES  M/A  OMRSD OFFLINE  EXERCISE BACKUP DRIVE SWITCH. VERIFY BACKUP COMMAND VOLTAGES FOR EACH SWITCH POSTION  AT DAC PANEL OUTPUT.  OMRSD ONLINE INSTALLATION  EXERCISE BACKUP BRIVE SWITCH VERIFY BACKUP COMMAND VOLTAGES FOR EACH SWITCH POSTION AT LONGERON INTERFACE.  OMRSD ONLINE TURNAROUND  IN BACKUP MODE, DRIVE WRIST ROLL IN  *VE AND -VE DIRECTIONS

PREPARED BY: MFMG SUPERCEDING DATE: 11 SEP 86 APPROVED BY: DATE: